Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE8437/1

Work Order Type: Weatherization Audit Name: Audit DE8437

CLIENT INFORMATION

Client Name: Address:

Client ID: Client 50005DE8437

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Alt. Client ID:

	<i>Measure</i> 1 Inf	iltration Redctn			Componen	its			Inspected
C	1. Sea 2. We 3. Pat 4. Ret 5. Rep 6. We 7. Doo 8. Bloo 9. Gla	IFILTRATION MEASURES at Plumbing penetrations atherstrip Front and side do ch floor child's bedroom ape 10ft of supply ducts place Broken panes W10, Watherstrip windows between sweep Front and side dock and seal AC W 8 ze Windows W7, W10 ap all 7 boots - seal with m	oors W3 n meeting ors), W7			
	10 111	ap all 7 booto Godi William	idolio lapo	and o	Estimated 2	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
C	other Detail								
				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:				-				

/	Measure 2 DW	H Tank Insulation			Componen	ts			Inspected
C	omment Old Bo	x style water heater in kito	chen made	by Rh	ieem				
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
0	ther Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Measure 3 DW	/H Pipe Insulation			Componen	ts			Inspected
		/H Pipe Insulation			Componen Estimated			Actual	Inspected
C		/H Pipe Insulation Description / Comment	Units	Qty	-		Qty		Inspected
C (omment		<i>Units</i> Each		Estimated	·	Qty	Actual	
# 1	omment Material / Labor	Description / Comment		Qty	Estimated	·	Qty	Actual	
# 1 2	omment Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	·	Qty	Actual	
C (4)	Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	·	Qty	Actual	
# 1 2	Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	·	Qty	Actual	
C (4)	Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated	·		Actual	

Measure 4 Floo	or Ins. R-19			Componen	ts Crawl	-960 sc	q,ft	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	960					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
Measure 5 Atti	c Ins. R-38			Componen		· 960 sc		Inspected
Measure 5 Atti Comment		Unito		Estimated			Actual	
Measure 5 Atti Comment # Material / Labor	C Ins. R-38 Description / Comment Attic Insulation - Blown Cellulose - R-38	<i>Units</i> SqFt	Qty 960	-		960 so		Inspected Total
Measure 5 Atti Comment # Material / Labor	Description / Comment Attic Insulation - Blown		Qty	Estimated			Actual	
Measure 5 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated			Actual	
Measure 5 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown	SqFt	Qty 960	Estimated		Qty	Actual	

Measure 6 Wall	Insulation			Componen	ts Back,l uth	Front,N	orth,So	Inspecte
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	827.9					
Other Detail								
			Measure	Sub Total:] .	Sub Total:	
	Detector			Componen				Inspecte
Comment		Units		Estimated		Qty	Actual	Inspecte
Comment # Material / Labor	Detector Description / Comment CO monitor	<i>Units</i> Each	Qty 1	-		Qty		
Comment * Material / Labor Health and Safety Items	Description / Comment		Qty	Estimated		Qty	Actual	
Comment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Comment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated			Actual	

•	or Barrier Needed sement/CrawIspace)			Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						_		
			Measur	e Sub Total:			Sub Total:	
	ted Vent-A-Hood to Incl eceptacle	ude Firdo	own	Component Estimated			Actual	Inspected
& R		ude Firdo <i>Unit</i> s	Qty			Qty		Inspected Total
& Ro Comment	Description / Comment			Estimated		Qty	Actual	
& Ro Comment # Material / Labor 1 Health and Safety	Description / Comment	Units	Qty	Estimated		Qty	Actual	
& Ro Comment # Material / Labor 1 Health and Safety Items	Description / Comment Material	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
& Ro Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Material	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
& Ro Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Material	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
& Ro Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Material	Units Each Each	Qty 1 1	Estimated			Actual	